

**ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULE - SREF 2014 & F.A.C. 69A-58  
FISCAL YEAR 2016-2017**

**College Facility:** South Florida State College      **Fire District:** DeSoto County  
**SCHOOL / FACILITY:** Desoto Campus  
**ADDRESS:** 2251 NE Turner Ave, Arcadia, FL 34266

**# OF SERIOUS FIRE SAFETY VIOLATIONS** 0

**# OF NON-SERIOUS FIRE SAFETY VIOLATIONS** 0

\_\_\_\_\_  
FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION)


Walter D. Spann, Jr. (Municipal Fire Inspector)  
COLLEGE BOARD FIRESAFETY INSPECTOR NAME PRINTED

March 20, 2017  
INSPECTION DATE

\_\_\_\_\_  
FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION)

Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-757-7205  
INSPECTOR ADDRESS & PHONE NUMBER

\_\_\_\_\_  
SIGNATURE DATE      FIRE INSPECTOR CERTIFICATION NUMBER

 3/23/2017  
COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE

62373  
FIRE INSPECTOR CERTIFICATION NUMBER

**LOCATION:**

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are affixed above the door leading into that particular room. Or if the deficiency in an area other than an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavillion, etc.

South Florida State College has met the requirements of F.S.S. 1013.12(2)(d):  YES     NO

Approval of Reports by Board (Including Letter)  YES     NO

**THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.**

Glenn W. Little  
FACILITY ADMINISTRATOR NAME PRINTED

Vice President for Administrative Services  
FACILITY ADMINISTRATOR TITLE

\_\_\_\_\_  
FACILITY ADMINISTRATOR SIGNATURE

May 9, 2017  
SIGNATURE DATE





**ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULE - SREF 2014 & F.A.C. 69A-58  
FISCAL YEAR 2016-2017**

**College Facility:** South Florida State College      **Fire District:** Hardee County  
**SCHOOL / FACILITY:** Hardee Campus 265  
**ADDRESS:** 2968 US Highway 17 North, Bowling Green, FL 33834

**# OF SERIOUS FIRE SAFETY VIOLATIONS** 0

**# OF NON-SERIOUS FIRE SAFETY VIOLATIONS** 0

\_\_\_\_\_  
FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION)

Walter D. Spann, Jr. (Municipal Fire Inspector)  
COLLEGE BOARD FIRESAFETY INSPECTOR NAME PRINTED

March 29, 2016  
INSPECTION DATE

\_\_\_\_\_  
FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION)

Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-757-7205  
INSPECTOR ADDRESS & PHONE NUMBER

\_\_\_\_\_  
SIGNATURE DATE      FIRE INSPECTOR CERTIFICATION NUMBER

 4/1/2016  
COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE

62373  
FIRE INSPECTOR CERTIFICATION NUMBER

**LOCATION:**

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are affixed above the door leading into that particular room. Or if the deficiency in an area other than an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavillion, etc.

South Florida State College has met the requirements of F.S.S. 1013.12(2)(d):  YES     NO

Approval of Reports by Board (Including Letter)  YES     NO

**THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.**

Glenn W. Little  
FACILITY ADMINISTRATOR NAME PRINTED  
Vice President for Administrative Services  
FACILITY ADMINISTRATOR TITLE

\_\_\_\_\_  
FACILITY ADMINISTRATOR SIGNATURE  
May 9, 2017  
SIGNATURE DATE







CODE NUMBER	Insp. Initials	SREF 2016/2017 Fire Safety Deficiencies - South Florida State College - Highlands Campus			Prior Times Cited	Deficiency Corrected By	Date Deficiency Corrected	Line No.
		Location, Deficiency Description						
	JB	A-Bldg.: No deficiencies noted						1
	JB	B Bldg.: No deficiencies noted						2
	JB	C1/C2 Bldg: No deficiencies noted						3
	JB	D Bldg.: No deficiencies noted						4
	JB	E Bldg.: No deficiencies noted						5
	JB	F Bldg.: No deficiencies noted						6
	JB	G Bldg.: No deficiencies noted						7
	JB	H Bldg.: No deficiencies noted						8
	JB	I-Bldg.: No deficiencies noted						9
	JB	J Bldg.: No deficiencies noted						10
	JB	K/K1 Bldg.: No deficiencies noted						11
	JB	L Bldg.: No deficiencies noted						12
	JB	M Bldg.: No deficiencies noted						13
	JB	N Bldg.: No deficiencies noted						14
	JB	O Bldg.: No deficiencies noted						15
	JB	P Bldg.: No deficiencies noted						16
	JB	R1/R2 Bldg.: No deficiencies noted						17
	JB	S Bldg.: No deficiencies noted						18
	JB	T/T1 Bldg.: No deficiencies noted						19
	JB	UC Bldg.: No Deficiencies noted						20
	JB	X Bldg.: No deficiencies noted						21
	JB	X1-Bldg.: No deficiencies noted						22
	JB	X2 Bldg.: No deficiencies noted						23
	JB	Y Bldg.: No deficiencies noted						24
	JB	CC Bldg.: No deficiencies noted						25
	JB	DD Bldg.: No Deficiencies noted						26
	JB	001-Tennis Courts: No deficiencies noted						27
	JB	002-Tennis Courts: No deficiencies noted						28
	JB	0010- Concession: No deficiencies noted						29
	JB	0011- Storage/Dugout: No deficiencies noted						30









**ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULE - SREF 2014 & F.A.C. 69A-58  
FISCAL YEAR 2016-2017**

**College Facility:** South Florida State College      **Fire District:** Highlands County  
**SCHOOL / FACILITY:** Lake Placid Campus 266  
**ADDRESS:** 500 East Interlake Blvd., Lake Placid, FL 33852

**# OF SERIOUS FIRE SAFETY VIOLATIONS** 0

**# OF NON-SERIOUS FIRE SAFETY VIOLATIONS** 0

\_\_\_\_\_  
FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION)


Walter D. Spann, Jr. (Municipal Fire Inspector)  
COLLEGE BOARD FIRESAFETY INSPECTOR NAME PRINTED

March 20, 2017  
INSPECTION DATE

\_\_\_\_\_  
FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION)

Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-757-7205  
INSPECTOR ADDRESS & PHONE NUMBER

\_\_\_\_\_  
SIGNATURE DATE      FIRE INSPECTOR CERTIFICATION NUMBER

 3/23/2017  
COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE

62373  
FIRE INSPECTOR CERTIFICATION NUMBER

**LOCATION:**

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are affixed above the door leading into that particular room. Or if the deficiency in an area other than an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavillion, etc.

South Florida State College has met the requirements of F.S.S. 1013.12(2)(d):  YES     NO

Approval of Reports by Board (Including Letter)  YES     NO

**THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.**

Glenn W. Little  
FACILITY ADMINISTRATOR NAME PRINTED  
Vice President for Administrative Services  
FACILITY ADMINISTRATOR TITLE

\_\_\_\_\_  
FACILITY ADMINISTRATOR SIGNATURE  
May 9, 2017  
SIGNATURE DATE













**ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULE - SREF 2014 & F.A.C. 69A-58  
FISCAL YEAR 2016-2017**

**College Facility:** South Florida State College      **Fire District:** Various  
**SCHOOL / FACILITY:** Off Campus Sites  
**ADDRESS:** Varies - See Report

# OF SERIOUS FIRE SAFETY VIOLATIONS 0

# OF NON-SERIOUS FIRE SAFETY VIOLATIONS 0

\_\_\_\_\_  
FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION)


Walter D. Spann, Jr. (Municipal Fire Inspector)  
COLLEGE BOARD FIRESAFETY INSPECTOR NAME PRINTED

March 20, 2017  
INSPECTION DATE

\_\_\_\_\_  
FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION)

Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-757-7205  
INSPECTOR ADDRESS & PHONE NUMBER

\_\_\_\_\_  
SIGNATURE DATE      FIRE INSPECTOR CERTIFICATION NUMBER

 3/23/2017  
COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE

62373  
FIRE INSPECTOR CERTIFICATION NUMBER

**LOCATION:**

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are affixed above the door leading into that particular room. Or if the deficiency in an area other than an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavillion, etc.

South Florida State College has met the requirements of F.S.S. 1013.12(2)(d):  YES     NO

Approval of Reports by Board (Including Letter)  YES     NO

**THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.**

Glenn W. Little  
FACILITY ADMINISTRATOR NAME PRINTED  
Vice President for Administrative Services  
FACILITY ADMINISTRATOR TITLE

\_\_\_\_\_  
FACILITY ADMINISTRATOR SIGNATURE  
May 9, 2017  
SIGNATURE DATE



